

The Sheafhouse, Sherborne – A Grade II Listed Building (photos taken on 29-07-2026)



Gable on the western elevation. Note open skylight and concrete replacement slates to the right of the gable.



Western elevation. Note holes in the roof, missing / slipped slates and missing ridge tiles.



Western elevation roof deterioration: missing slates, open voids, collapsed ridge, replacement concrete slates.



Western elevation roof deterioration: as above and missing ridge tiles.



Stone date plaque on gable: 1831



East facing elevation on interior courtyard showing rotten and collapsed timber lintel between stone piers.



Interior detail: western end of northern barn showing collapsed roof truss.



Interior detail: west facing roof of western barn showing rotten rafters and open void. Note original roof Trusses with curving tie beams.



Interior detail: south facing roof of northern barn showing rotten and collapsed roof truss and open void.



Interior detail within the northern barn showing active badger sett and excavations within the floor. Note the original timber stalls to the right.