

Sheafhouse Collapse – Central part of the eastern wing of the building (Photos taken on 7/09/2026)



View from east of the building.



Internal view



Internal view



Internal view



Internal view